Field Service Bulletin No. 50

Order No.: DD+DIS267.01E

1 piece UT9ON MA1

ADC Compact

Type 5145 / 100/101/140
5145 / 200/201/240

Rating			When?		
safety relevant	reliability	new function	immediately	next service	as required
	X				**X**

Please file this document in Section 13 of your technical documentation

New vacuum pump introduced

What is new?

- The vacuum-pump switch has been redesigned by changing the spring position in the switch.
- The brass screw on the top is no longer adjustable, because it caused too much pressure on the spring.
  The effect of adjustment actions is now directly on the vacuum-pump switch. This adjustment is performed in production; Therefore, no adjustment is required in the field.

Logistic

The old vacuum-pumps are no longer delivered to the field. They were sent back to the manufacturer to be modified to the new status.

The spare part number stays the same as it was for the standard vacuum-pump. (CM+9.5145.9310.0)

printed in Germany 01 / 2002

AGFA